


Step1


Put out 3 cables and connect to LS. Create station at -60. Start measure.
Continue putting out 3 more cables while the instrument operates.



Step2

Re-arrange to full system. Create station at 0. Start measure.

Note: No cable joint between cable 3 and 4. All cable joint with ring mark towards device (es or ls)



Step 3 (N-1)

Do roll along with as many cables as needed.

If performing roll-along with 1 cable add +20 to station position, for 2 cables add +40 to station position

Last step

Complete the last cable

